


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 01-97 To (mo./yr.) 12-97
2. DOGM File Number (Mine No): 510471034
3. Mine Name: YERIAN
4. Mineral(s) Mined (or permitted to mine): GOLD
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
LOTS 1, 2 & 3
1/4, 1/4, 1/4, Section 2, Township 7S, Range 21E
1/4, 1/4, 1/4, Section 11, Township 7S, Range 21E
1/4, 1/4, 1/4, Section, Township, Range
7. Name of Operator or Company: GOLDEN EAGLE MINES LTD
8. Permanent Street Address: 13532-111 ST.
City, State, Zip: EDMONTON, ALTA. T5E 4Z8
Phone: 403-4753954
9. Company Representative (or designated operator):
Name: WALTER BABIY
Title: _____
Business Address: Box 126 CHERHILL
City, State, Zip: CHERHILL ALTA. T0E 0J0
Phone: 403 785 2663
☒ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☐ No ☒
2. If active, how much ore or mineral was mined? _____
3. If inactive, what year was the mine last active? _____

3. How much **additional acreage** was disturbed during the past year? _____
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
- _____
- _____
- _____
5. How much acreage was **reclaimed** during the past year? _____
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
- _____
- _____
- _____
7. What is the **total disturbed acreage** at years end? _____ 5?
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
- _____
- _____
- _____

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

NESTOR PUKALO

Title of Operator:

PRES

Signature of Operator:

Nestor Pukalo


Date:

Jan 27 1998

RECEIVED
FEB 02 1998
DIV. OF OIL, GAS & MINING



11/27/98 YERIAN MINE AREA PHOTOS - FROM BLM



199750455

YERIAN MINE RECLAMATION SITE

GREEN RIVER - HORSESHOE BEND

Section 35, Township 6 South, Range 21 East

Section 2, Township 7 South, Range 21 East

Uintah County, Utah

Encl 1 of 1.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT


Vernal Field Office
170 South 500 East
Vernal, Utah 84078-2799

Phone: (435) 781-4400
Fax: (435) 781-4410

IN REPLY REFER TO:

3809
76092
(UT08300)

January 30, 1998



Tony Gallegos
State Of Utah
Division of Oil, Gas, and Mining
1594 West North Temple, Suite 1210
Box 145801
Salt Lake City, Utah 884114-5801

Re: **Yerian Mine Status** and ~~Plan of Operation Submission~~

Dear Tony:

I wanted to inform you that a natural resources protection specialist from this office was in and about the Horseshoe Bend area on 1/27/98. He took the enclosed 3 photographs (index map of locations, numbers, and direction of photos is enclosed; descriptions are on the rear). The location is in the same condition as when we had the joint on site some months ago.

~~Also, SF Phopshates has filed a plan of operation with the BLM to drill a water well to provide water for the increased volume of product being milled (plan enclosed; assigned serial no. UTU 76092). If the well produces enough water, the well site will be enclosed with a small building which will be fenced. An overhead electric line and a buried water line will be run along an existing two track road which runs north-south between the well site and SF's private property. This is a plan with us due to the presence of an area of critical environmental concern; it is probably a small mine operation under State rules. The plan is incomplete and we have asked for more information in an 11/21/97 certified letter.~~

If you have any questions, please contact me at (435) 781-4501.

Sincerely,

Peter K. Sokolosky
Geologist, Vernal Field Office

enclosures